

# Concrete Floor Covering Failures

*B. Lee Lawrence, P.E.*

*Wiss, Janney, Elstner Associates, Inc.*

*13581 Pond Springs Road, Suite 107*

*Austin, Texas 78729*

# Introduction

- *Background:*
  - *Contributors to failure*
  - *Mechanisms of failure*
- *Unique Floor Covering Failure Case Studies:*
  - *Alkali-silica reaction*
  - *Sulfate attack*
  - *Osmotic pressure*
  - *Chemical attack (alkaline hydroxide)*

# Contributors to Failure

*“The Commonly Accused Culprits”*

- *Improper Application and Material Problems*
- *Vapor and Vapor Pressure*
- *Moisture (liquid)*

# Application and Material Problems

- *Application Issues:*
  - *Slab construction/design deficiencies*
  - *Improper surface preparation*
  - *Installation at elevated moisture-vapor transmission rates*
  - *Improper mixing*
- *Material Problems*
  - *Material incompatibility*
  - *Improper formulation*

# Vapor and Vapor Pressure

- *Vapor - “ a substance in the gaseous state, as distinguished from solid or liquid matter”*
- *Water Vapor Pressure – caused by a water vapor gradient, e.g. movement from areas of high humidity to areas of low humidity*
  - *Moisture-vapor pressure in a floor slab is generally very low relative to a well adhered floor covering*
  - *Moisture-vapor emission rates can be assessed qualitatively (ASTM D4263 - plastic sheet method) and quantitatively (ASTM F1869 - anhydrous calcium chloride method)*
- *Moisture vapor can condense to water in a slab.*

# Sources of Water in a Slab on Grade

- *Moisture - If the concrete is “dry” at the time of application and remains so during service of the floor covering system, most types of floor covering failures will never occur!*
- *Sources of Water – residual mixing water from the concrete, curing water, washing water, rainfall, condensation of water vapor, and water from slab substrate via hydrostatic pressure, capillary rise, or osmosis. (Ref. June/April 2003 Concrete International)*
- *Most floor coverings are sensitive to presence of moisture at application and some continue to be sensitive to moisture even after application and curing*
- *The availability of moisture can cause other mechanisms of distress to occur, which can be disruptive to floor coverings*

# Mechanisms of Failure

- *Alkali-silica Reaction*
- *Sulfate Attack*
- *Osmotic Pressure*
- *Chemical Attack (alkaline hydroxide)*

# Failure Mechanisms

## *Alkali-Silica Reaction (ASR)*

- *A reaction between reactive siliceous aggregate particles and hydroxyls of the pore solution*
- *High alkali content of portland cement*
- *Reactive siliceous aggregate*
- *Sufficient moisture*





# Failure Mechanisms

## *Sulfate Attack*

- *A reaction between sulfate ions normally from an external or internal source and calcium aluminate and calcium hydroxide of the cement paste*
- *Sulfate attack can cause expansion, cracking, and crumbling of paste*



# Failure Mechanisms

## *Osmotic Blistering*

- *Associated with osmosis, in which a solvent (water) passes through a semi-permeable membrane (concrete surface) from a dilute solution to a more concentrated solution*
- *Liquid volume increases as osmotic pressure builds up, causing debonding/blistering*



# Failure Mechanisms

## *Chemical Attack (Saponification)*

- *Portland cement and wet portland cement concrete have a high pH typically ranging between 13 and 14*
- *Calcium, sodium, and potassium hydroxide are soluble constituents of portland cement*
- *Non-carbonated surfaces or surfaces contaminated with transported alkaline hydroxides can result in a high pH environment that can cause degradation of some adhesives*




# Typical Investigation Methods



- *Condition survey (look, touch, smell...)*
- *Moisture-vapor emission testing (ASTM F1869)*
- *Pull-off testing (ASTM D4541, ACI 503R)*
- *Concrete Petrography - To estimate mix proportions and identify problems associated with mixing, finishing, and deleterious distress mechanisms*
- *Chemical studies for determining pH and compositional characteristics of concrete surfaces (ASTM D4262, XRD/SEM-EDX)*



w/c



# Air voids



# Case Study No. 1 - ASR Induced Floor Covering Failure

## *General Observations:*


- *Epoxy coating applied on a two-year-old concrete slab with vapor barrier underneath*
- *Scaling and blistering observed within several months of application*
- *Cores were taken and examined petrographically*
- *Concrete was of good quality*
- *Near-surface ASR was identified involving fine rhyolite particles*
- *No ASR detected at the interior of the concrete*

## Epoxy floor system





# cementitious



## Region of debonded epoxy




## Concrete entrance




## Typical surface scaling in exterior concrete




## Sample cross-section at disbonded area




## ASR gel at interface



## Reactive aggregate near surface



## ASR gel on concrete surface





# ASR Induced Floor Covering Failure

*Probable causes of near-surface ASR:*

- *Segregation resulting in reactive aggregate concentrated only in the near-surface region*
- *Significant moisture gradient with high near-surface moisture content*
- *Alkali gradient*

# ASR Induced Floor Covering Failure

*Chemical testing: Acid soluble and water soluble alkali content*

<i>Depth (in.)</i>	<i>Na<sub>2</sub>O<sub>eq</sub> (acid soluble)</i>	<i>Na<sub>2</sub>O<sub>eq</sub> (water soluble)</i>
<i>0 to 1/2</i>	<i>0.18%</i>	<i>0.05%</i>
<i>3-1/2 to 4</i>	<i>0.16%</i>	<i>0.031%</i>

*Bleed water and/or upward moisture movement transported alkalis to the near-surface region of the concrete.*

# Case Study No. 2 - Floor Covering Failures due to Sulfate Attack


## *General Observations:*

- *Vinyl tiles and sheet vinyl were installed on a slab-on-grade less than two years old*
- *Localized debonding occurred within a few months*
- *Petrographic examinations were performed on concrete cores taken from the slab. The concrete was normal.*
- *A shrinkage compensating mortar was present above the concrete*
- *Vinyl floor covering was installed with an adhesive that was applied with a notched trowel*
- *Abundant ettringite deposits were observed between the strips of adhesive and in the leveling mortar*


## Concrete with leveling mortar




## Multiple layers of leveling mortar



## Band of ettringite in leveling mortar



## Ettringite along adhesive strips



## Ettringite and adhesive





# Floor Covering Failures due to Sulfate Attack

## *Cause of Failure:*

- *The shrinkage compensating mortar contained abundant calcium aluminate and calcium sulfate*
- *Moisture in the adhesive resulted in dissolving and reprecipitation of these components, forming ettringite in the interface*
- *The resulting internal sulfate attack caused the debonding of the vinyl flooring*

## Case Study No. 3 - Floor Covering Failure Caused by Osmotic Blistering

### *General Observations:*

- *A six-year-old polymeric coating in a wastewater pit exhibited debonding and blistering on the walls and floor of the pit*
- *Coating included a thin epoxy base coating and a “high-build” polymeric top coat with a total applied thickness ranging between 60 to 80 mils*
- *Surface preparation by sand blasting*
- *Moisture desiccation employed by forced-air dehumidifiers*
- *Moisture-vapor emissions exceeded manufacturer’s recommended limits at time of application*

## Case Study No. 3 - Floor Covering Failure Caused by Osmotic Blistering – cont'd

### *General Observations:*

- *Application followed all other manufacturer's recommendations*
- *Petrographic examination indicated that the concrete was of good quality*
- *Blisters were often fluid-filled and under pressure*
- *Disbondment observed between epoxy base coat and concrete and between top coat and epoxy base coat*
- *Indication of possible formulation problems*

## Breach of coating



## Typical fluid-filled blisters



## Blisters under the ceiling



## Holidays below the coating




## Blister on a core from the floor






## Voids in coating indicating possible material problem




## Blister between top coat and epoxy base coat



## Liquid from blister




## Crystals from evaporated blister fluid



# Mechanism of Osmotic Blistering


*On the floor and wall surfaces, the coating and/or the primer acts as a semipermeable membrane. Contaminants from the concrete, or solvents from the coatings left on the concrete surface, and moisture inside the concrete form the osmotic blister.*



# Floor Covering Failure Caused by Osmotic Blistering

*On the floors and walls, both the concrete surface and the coating and/or the primer act as a semipermeable membrane. Contaminants are likely from concrete or coating solvents.*

*Condensed water from tank or moisture in concrete are likely contributors to the osmotic blistering.*




# Case Study No. 4 - Floor Covering Failure Caused by Chemical Attack

## *General Observations:*

- *Laminated rubber-like sheet installed with a water-based adhesive;*
- *A relatively new installation (less than one year)*
- *The slab was directly underlain by a layer of sand with 6 mil vapor retarder located beneath the bed of sand*
- *The sand had an approximate 11 percent moisture content; and*
- *When removed, adhesive was found to have liquidized due to a high moisture and alkali condition causing saponification of vinyl acetate-based polymer and phthalate ester plasticizing components in the adhesive*

## Liquidized adhesive





## Discussion and Conclusions

- *Free moisture and moisture-vapor emission is often not the sole contributing cause to floor covering failure*
- *Moisture and condensed vapor emissions can provide necessary moisture for a variety of problems including near-surface ASR, sulfate attack, osmotic blistering, concrete-borne chemical attack, and other forms of distress mechanisms*
- *Manufacturers' moisture-vapor emission limits may not always guarantee against these types of failure mechanisms*
- *Use of floor covering systems that are vapor barriers should be properly designed before installation*

**Thank You!**